

Facility Condition Report								
Facility	Age	Location	Square Footage	Overall Condition	Usage	Number of Rooms	New	
CTK Hall	1967	1690 E 17th	10,552			18 rooms 6 storage	5 – New - <b>New or like-new condition</b> ; no issues to report; no expected failures	
							4 – good - <b>Good condition</b> ; no reported issues or concerns	Good
							3 – fair - <b>Average wear for building age</b> ; not new but no issues to report	Fair
							2 – poor - <b>Worn from use -end of expected lifecycle</b> . Plan for replacement/upgrade	Poor
							1 – critical - <b>Extremely worn or damaged, could be potential safety issues, replacement w/in 2 yrs.</b>	Critical
							NA - Not Applicable	
	<b>TYPE</b>	<b>5</b>	<b>4</b>	<b>3</b>	<b>2</b>	<b>1</b>		<b>Comments/Recommendations</b>
<b>HVAC</b>								
Condition	Critical							One roof HVAC unit was not upgraded when others were and requires replacement
Type of heat	Gas Forced							4 HVAC Units have been upgraded.
Type of air conditioning	Electric							
<b>ROOF</b>								
Condition	Poor							There is a significant leak into the utility room (fortunately a floor drain exists within that room) that has been chased by various roofing contractors for many years.
<b>ELECTRICAL</b>								
Condition	Fair							
Lighting	Fair							Ballasts run approximately \$400 each and we are spending approximately \$2k/yr. replacing them. A campaign to replace ballasts with LED lights is recommended for the entire hall
<b>PLUMBING</b>								
Condition	Good							
<b>SECURITY</b>								
Condition	Critical							substandard system exists but is being upgraded with modern technology in FY'18. Should be completed by the end of June 2018
<b>EXTERIOR</b>								
Exterior composition of the building	Excellent							
Are the windows in good condition	Excellent							
Are the doors adequate and secure	Excellent							
Condition of concrete sidewalks and stairs	Good							One minor issue with water pooling and concrete cracking is observed on the slab right outside the main entrance door.
Condition of parking lot and any pavement	Excellent	LEGACY						
Condition of curbs	Good							
<b>INTERIOR</b>								
Condition of interior flooring	Poor							Classroom, office and hallway carpet requires replacement
Condition of interior walls	Good							
General cosmetic condition	Good							
If appliances, what condition	Good							
Fridge	Good							
Dishwasher	Good							
Freezer	Good							
Oven/cooktops	Good							
Cabinets/counters	Good							

Facility Condition Report								
Facility	Age	Location	Square Footage	Overall Condition	Usage	Number of Rooms	New	5 – New - <b>New or like-new condition</b> ; no issues to report; no expected failures
<b>CTK Rectory</b>	1967	1696 E 17th	2,679				Good	4 – good - <b>Good condition</b> ; no reported issues or concerns
							Fair	3 – fair - <b>Average wear for building age</b> ; not new but no issues to report
							Poor	2 – poor - <b>Worn from use -end of expected lifecycle</b> . Plan for replacement/upgrade
							Critical	1 – critical - <b>Extremely worn or damaged, could be potential safety issues</b> , replacement w/in 2 yrs.
								NA - Not Applicable
	<b>TYPE</b>	<b>5</b>	<b>4</b>	<b>3</b>	<b>2</b>	<b>1</b>		<b>Comments/Recommendations</b>
<b>HVAC</b>								
Type of heat	Gas							Furnace is 30+ years old and should be planned for replacement
Type of air conditioning	None							
<b>ROOF</b>								
Condition								Roof is 30+ years old and should be planned for replacement
Condition of gutters and heat tape								
<b>ELECTRICAL</b>								
Condition	Good							
Lighting	Good							Mixed Fluorescent & LED
<b>PLUMBING</b>								
Condition	Good							
<b>SECURITY</b>								
Condition	No System							
<b>EXTERIOR</b>								No exterior issues noted.
Exterior composition of the building	Good							
Are the windows in good condition	Good							
Are the doors adequate and secure	Good							
Condition of concrete sidewalks and stairs	Good							
Condition of parking lot and any pavement	Good							
Condition of curbs	Good							
<b>INTERIOR</b>								
Condition of interior flooring	Fair							Flooring is dated throughout
Condition of interior walls	Fair							
General cosmetic condition	Fair							
If appliances, what condition	Good	<b>LEGACY</b>						
Fridge	Good	<b>LEGACY</b>						
Dishwasher	Good	<b>LEGACY</b>						
Freezer	Good	<b>LEGACY</b>						
Oven/cooktops	Fair							Kitchen is functional though somewhat dated in appearance
Cabinets/counters	Fair							

Facility Condition Report								
Facility	Age	Location	Square Footage	Overall Condition	Usage	Number of Rooms	New	
<b>CTK Church</b>	1967	1696 E 17th	9,600				5 – New - <b>New or like-new condition</b> ; no issues to report; no expected failures	
							4 – good - <b>Good condition</b> ; no reported issues or concerns	
							3 – fair - <b>Average wear for building age</b> ; not new but no issues to report	
							2 – poor - <b>Worn from use -end of expected lifecycle</b> . Plan for replacement/upgrade	
							1 – critical - <b>Extremely worn or damaged, could be potential safety issues</b> , replacement w/in 2 yrs.	
							NA - Not Applicable	
	<b>TYPE</b>	<b>5</b>	<b>4</b>	<b>3</b>	<b>2</b>	<b>1</b>		<b>Comments/Recommendations</b>
<b>HVAC</b>								
Condition	Excellent							Replaced in 2010
Type of air conditioning	None							AC was not added during upgrade of furnace, will be a significant cost (appx. \$150k) to add now.
<b>ROOF</b>								
Condition	Critical							Significant issue related to the transition portion of sloped roof to “flat” portion over entrance vestibule. This was previously identified by subcontractor to need replacement within the next 5 years. Other areas have been upgraded; main roof replaced circa 1990, HVAC annex replaced 2010, Office area replaced with membrane 2017.
<b>ELECTRICAL</b>								
Condition	Good							
Lighting	Good							Mixed Fluorescent & LED
<b>PLUMBING</b>								
Condition	Excellent							Installation of a deep sink is required to support janitorial efforts.
<b>SECURITY</b>								
Condition	Critical							Substandard system exists but is being upgraded with modern technology in FY’18. Should be completed by the end of June 2018
<b>EXTERIOR</b>								
Exterior composition of the building	Brick							
Are the windows in good condition	Good							
Are the doors adequate and secure	Good							
Condition of concrete sidewalks and stairs	Good							
Condition of parking lot and any pavement	Good	<b>LEGACY</b>						
Condition of curbs	Good							
Potential Major Maintenance or Upgrade Items:	Wood Fence							Privacy fence around the church is aging and should be considered for replacement.
<b>INTERIOR</b>								
Condition of interior flooring	Poor							The interior of the church seating space and altar should be considered for a major upgrade within 5 years. Pews are held together by 2x4 cribbing, flooring is in poor shape, carpet is showing signs of significant wear (was replaced in appx. 2010), the vertical trim boards on the altar are skewed (drying out/aging), and in general our standards are not being met. The office area and mass preparation areas do not show as much wear.
Condition of interior walls	Fair							Carpet and other flooring showing significant signs of wear.
General cosmetic condition	Poor							Dated and in need of renovation.
								Generally, the interior of the church is in poor cosmetic condition and a major renovation should be planned for.

Facility Condition Report								
Facility	Age	Location	Square Footage	Overall Condition	Usage	Number of Rooms	New	5 – New - <b>New or like-new condition</b> ; no issues to report; no expected failures
<b>HR Hall</b>	1959	150 8th	7,249				Good	4 – good - <b>Good condition</b> ; no reported issues or concerns
							Fair	3 – fair - <b>Average wear for building age</b> ; not new but no issues to report
							Poor	2 – poor - <b>Worn from use -end of expected lifecycle</b> . Plan for replacement/upgrade
							Critical	1 – critical - <b>Extremely worn or damaged, could be potential safety issues</b> , replacement w/in 2 yrs.
								NA - Not Applicable
	<b>TYPE</b>	<b>5</b>	<b>4</b>	<b>3</b>	<b>2</b>	<b>1</b>		<b>Comments/Recommendations</b>
<b>HVAC</b>								
Condition								Heating system is the original hot water boiler and is constantly repaired along with periodic maintenance.
Type of air conditioning	None							
<b>ROOF</b>								
Condition	Excellent	<b>LEGACY</b>						
<b>ELECTRICAL</b>								
Lighting	Fair							80% LED, change would yield a cost savings if LED changeout campaign was undertaken
<b>PLUMBING</b>								
Condition								Adequately maintained, but dated.
<b>SECURITY</b>								
Condition	Excellent	<b>LEGACY</b>						
<b>EXTERIOR</b>								
Exterior composition of the building	Brick							
Are the windows in good condition	Fair							Original windows in most cases, functional but dated.
Are the doors adequate and secure	Fair							Original doors in most cases, functional but dated.
Condition of concrete sidewalks and stairs	Good							
Condition of parking lot and any pavement	Excellent	<b>LEGACY</b>						
Condition of curbs	Excellent							
<b>INTERIOR</b>								
Condition of interior flooring	Fair							Cafeteria flooring original and in decent condition.
Condition of interior walls	Excellent							New paint -2016
General cosmetic condition	Excellent							
If appliances, what condition	Good							
Fridge	Fair							Original walk in circa 1958, functional.
Dishwasher	Good							
Freezer	Fair							
Over/cooktops	Excellent	<b>LEGACY</b>						
Cabinets/counters	Good							
Exhaust Fan	Excellent	<b>LEGACY</b>						

Facility Condition Report							
Facility	Age	Location	Square Footage	Overall Condition	Usage	Number of Rooms	New
HR Church	1949	905 S Lee Ave	7,890				5 – New - <b>New or like-new condition</b> ; no issues to report; no expected failures
							Good 4 – good - <b>Good condition</b> ; no reported issues or concerns
							Fair 3 – fair - <b>Average wear for building age</b> ; not new but no issues to report
							Poor 2 – poor - <b>Worn from use -end of expected lifecycle</b> . Plan for replacement/upgrade
							Critical 1 – critical - <b>Extremely worn or damaged, could be potential safety issues</b> , replacement w/in 2 yrs.
							NA - Not Applicable
	TYPE	5	4	3	2	1	Comments/Recommendations
<b>HVAC</b>							
Condition	gas boiler						The heating system is a significant concern. The church is served by a hot water gas fired boiler feeding radiant heat. The gas pilot light is on 24/7. The original 1948 vintage coal furnace was retrofitted to gas sometime in the past. The heating system is very inefficient.
Type of air conditioning	None						
<b>ROOF</b>							
Condition	Critical						The roof is a significant concern. The current cedar shingle roof was installed circa 1970's. The south facing shingles are showing wear do to sun exposure. With maintenance the roof is projected to last 5-7 years. \$25k to treat roof on 3-5 year frequency.
<b>ELECTRICAL</b>							
Condition	Fair						The electrical system dates to the building's 1949 construction. As it is an older building it is possible that problems may occur in the future.
Lighting	Excellent	LEGACY					All LED
<b>PLUMBING</b>							
Condition	Fair						The plumbing and sewer systems are a mixture of old and new. Copper, galvanized, and old cast iron sewer pipes all coexist. The city water supply lines are original are most likely galvanized pipe.
Lawn sprinkler system	Good						Repaired in 2016
<b>SECURITY</b>							
Condition	Fair						Security system needs to be updated to digital with outside coverage. \$15,000 for both facilities.
<b>EXTERIOR</b>							
Exterior composition of the building	Brick						Recently repaired
Are the windows in good condition	Good						
Are the doors adequate and secure	Good						
Foundation	Fair						Original, no issues noted.
Condition of concrete sidewalks and stairs	Good - 2016	LEGACY					
Condition of parking lot and any pavement	Fair						Some degradation noted in parking area
Condition of curbs	Fair						Some degradation noted in parking area
<b>INTERIOR</b>							
Condition of interior flooring	Good 2016	LEGACY					
Condition of interior walls	Good 2016	LEGACY					
General cosmetic condition	Good	LEGACY					Major renovation in 2017 addressed most if not all cosmetic issues within the church proper. Bathrooms in excellent condition.
<b>MISCELLANEOUS</b>							
General notes:							

Facility Condition Report								
Facility	Age	Location	Square Footage	Overall Condition	Usage	Number of Rooms	New	5 – New - <b>New or like-new condition</b> ; no issues to report; no expected failures
<b>HR Rectory</b>	1949	228 9th	5,323				Good	4 – good - <b>Good condition</b> ; no reported issues or concerns
							Fair	3 – fair - <b>Average wear for building age</b> ; not new but no issues to report
							Poor	2 – poor - <b>Worn from use -end of expected lifecycle</b> . Plan for replacement/upgrade
							Critical	1 – critical - <b>Extremely worn or damaged, could be potential safety issues</b> , replacement w/in 2 yrs.
								NA - Not Applicable
	<b>TYPE</b>	<b>5</b>	<b>4</b>	<b>3</b>	<b>2</b>	<b>1</b>		<b>Comments/Recommendations</b>
<b>HVAC</b>								
Condition	Good							
Type of air conditioning	None							
<b>ROOF</b>								
Condition	Critical							The roof is a significant concern. The current cedar shingle roof was installed circa 1970's. The south facing shingles are showing wear do to sun exposure. With maintenance the roof is projected to last 5-7 years. \$25k to treat roof on 3-5 year frequency.
<b>ELECTRICAL</b>								
Condition	Fair							Original wiring, service panel replaced in 2015.
Lighting	Good							Mixed Fluorescent & LED
<b>PLUMBING</b>								
Condition	Fair							Original pipes throughout, sewer line replaced, original city water supply line.
<b>SECURITY</b>								
Condition	Good							
<b>EXTERIOR</b>								
Exterior composition of the building	Brick							Recently repaired and in good shape
Are the windows in good condition	Good							
Are the doors adequate and secure	Good							
Foundation	Good							
Condition of concrete sidewalks and stairs	Good							
Condition of parking lot and any pavement	Good							
Condition of curbs	Good							
<b>INTERIOR</b>								
Condition of interior flooring	Poor							
Condition of interior walls	Poor							
General cosmetic condition	Poor							General cosmetic condition of interior rooms and kitchen is poor and does not meet parish standards. Major renovation recommended prior to arrival of new priest.
If appliances, what condition								
Fridge	Critical							
Dishwasher								
Oven/cooktops	Poor							
Cabinets/counters	Poor							

Facility Condition Report								
Facility	Age	Location	Square Footage	Overall Condition	Usage	Number of Rooms	New	5 – New - <b>New or like-new condition</b> ; no issues to report; no expected failures
<b>Holy Rosary School</b>	1968	175 9th	13,014			20	Good	4 – good - <b>Good condition</b> ; no reported issues or concerns
							Fair	3 – fair - <b>Average wear for building age</b> ; not new but no issues to report
							Poor	2 – poor - <b>Worn from use -end of expected lifecycle</b> . Plan for replacement/upgrade
							Critical	1 – critical - <b>Extremely worn or damaged, could be potential safety issues</b> , replacement w/in 2 yrs.
								NA - Not Applicable
	<b>TYPE</b>	<b>5</b>	<b>4</b>	<b>3</b>	<b>2</b>	<b>1</b>		<b>Comments/Recommendations</b>
<b>HVAC</b>								
Condition	Excellent	LEGACY						NONE 25 Year Guarantee
Type of air conditioning	Electric	LEGACY						
<b>ROOF</b>								
Condition	Excellent	LEGACY						NONE 25 Year Guarantee
<b>ELECTRICAL</b>								
Condition	Fair							NONE 25 Year Guarantee
Lighting	Excellent	LEGACY						
<b>PLUMBING</b>								
Condition	Fair							NONE 25 Year Guarantee
<b>SECURITY</b>								
Condition		LEGACY						NONE 25 Year Guarantee
<b>EXTERIOR</b>								
Exterior composition of the building	Brick							
Are the windows in good condition	Fair							Windows are mostly original, functional but not optimal insulating properties.
Are the doors adequate and secure	Fair							Doors are mostly original, functional.
Condition of concrete sidewalks and stairs	Good							
Condition of parking lot and any pavement	Excellent	LEGACY						
Condition of curbs	Excellent							
Foundation	Excellent							
<b>INTERIOR</b>								
Condition of interior flooring	Good							
Condition of interior walls	Excellent							
General cosmetic condition	Excellent							
<b>MISCELLANEOUS</b>								
General notes:	See Comments							WIFI system does not meet the needs of the school and should be addressed as soon as practical.
Asbestos	See Comments							Yes, sealed and contained, inspected every 6 months

Facility Condition Report								
Facility	Age	Location	Square Footage	Overall Condition	Usage	Number of Rooms	New	5 – New - <b>New or like-new condition</b> ; no issues to report; no expected failures
<b>Parish Office</b>	1950's	145 9th	4,252				Good	4 – good - <b>Good condition</b> ; no reported issues or concerns
							Fair	3 – fair - <b>Average wear for building age</b> ; not new but no issues to report
							Poor	2 – poor - <b>Worn from use -end of expected lifecycle</b> . Plan for replacement/upgrade
							Critical	1 – critical - <b>Extremely worn or damaged, could be potential safety issues</b> , replacement w/in 2 yrs.
								NA - Not Applicable
	<b>TYPE</b>	<b>5</b>	<b>4</b>	<b>3</b>	<b>2</b>	<b>1</b>		<b>Comments/Recommendations</b>
<b>HVAC</b>								
Condition	Good							
Type of air conditioning	Fair							Window units
<b>ROOF</b>								
Condition		LEGACY						
<b>ELECTRICAL</b>								
Condition	Fair							
Lighting	Fair							Mixed Fluorescent & LED
<b>PLUMBING</b>								
Condition	Fair							Original water main to street which is a concern, fixtures and baths functional, toilets original and no longer supported parts currently being replaced, showers on third floor not functional.
Are there showers	Fair							
<b>SECURITY</b>								
Condition	Fair							Simple and functional security system is in place. Dated, but works
<b>EXTERIOR</b>								
Exterior composition of the building	Brick							
Are the windows in good condition	Poor							Window are original and in very poor working condition
Are the doors adequate and secure	Poor							Doors are original and in very poor shape w exception of the couple replaced during updating
Condition of concrete sidewalks and stairs	Poor							Concrete flatwork and stairs will require replacement soon. Have been touched up and patched, but only temp fix.
Condition of curbs	Good							
<b>INTERIOR</b>								
Condition of interior flooring	Poor							Carpet and other flooring require replacement
Condition of interior walls	Good							
General cosmetic condition	Good							Some of the offices and first floor paint, trim, and doors were upgraded through Legacy. Much of the building still needs cosmetic attention, see issues listed.
If appliances, what condition	Fair							Appliances are dated and some not working well.
Fridge	Excellent							
Oven/cooktops	Fair							Appliances are dated and some not working well.



Facility Condition Report								
Facility	Age	Location	Square Footage	Overall Condition	Usage	Number of Rooms	New	5 – New - <b>New or like-new condition</b> ; no issues to report; no expected failures
Library	1947	168 9th	2,869				Good	4 – good - <b>Good condition</b> ; no reported issues or concerns
							Fair	3 – fair - <b>Average wear for building age</b> ; not new but no issues to report
							Poor	2 – poor - <b>Worn from use -end of expected lifecycle</b> . Plan for replacement/upgrade
							Critical	1 – critical - <b>Extremely worn or damaged, could be potential safety issues</b> , replacement w/in 2 yrs.
								NA - Not Applicable
	TYPE	5	4	3	2	1		Comments/Recommendations
<b>HVAC</b>								
Condition	hot water boiler							Original hot water boilers that undergo multiple failures per year and is becoming increasingly difficult to repair (parts availability).
Type of air conditioning	None							
<b>ROOF</b>								
Condition	Excellent	LEGACY						
<b>ELECTRICAL</b>								
Condition	Fair							
Lighting	Fair							All Fluorescent
<b>PLUMBING</b>								
Condition	Fair							Original city sewer line is a liability, city water line replaced in 2015
<b>SECURITY</b>								
Condition	Excellent							
<b>EXTERIOR</b>								
Exterior composition of the building	Siding							Contains asbestos, makes repairs and upgrades costly.
Are the windows in good condition	Good							
Are the doors adequate and secure	Good							
Condition of concrete sidewalks and stairs	Poor							Concrete stairs are failing and are a safety risk.
Condition of curbs	Fair							
<b>INTERIOR</b>								
Condition of interior flooring	Fair							
Condition of interior walls	Fair							
General cosmetic condition	Fair							Facility is in the asbestos program which makes cosmetic upgrades potentially expensive, upgraded paint, windows functional, carpet is old and needs to be replaced

Facility Condition Report								
Facility	Age	Location	Square Footage	Overall Condition	Usage	Number of Rooms	New	5 – New - New or like-new condition; no issues to report; no expected failures
STEM Facility	1927		800				Good	4 – good - Good condition; no reported issues or concerns
							Fair	3 – fair - Average wear for building age; not new but no issues to report
							Poor	2 – poor - Worn from use -end of expected lifecycle. Plan for replacement/upgrade
							Critical	1 – critical - Extremely worn or damaged, could be potential safety issues, replacement w/in 2 yrs.
								NA - Not Applicable
	TYPE	5	4	3	2	1		Comments/Recommendations
<b>HVAC</b>								
Condition	Critical							Original hot water boiler that undergoes multiple failures per year and is becoming increasingly difficult to repair (parts availability).
Type of air conditioning	None							
<b>ROOF</b>								
Condition	Good							
<b>ELECTRICAL</b>								
Condition	Fair							Original electrical wiring circa 1950's
Lighting	Fair							Fluorescent lighting throughout
<b>PLUMBING</b>								
Condition	Fair							
<b>SECURITY</b>								
Condition	None							
<b>EXTERIOR</b>								
Exterior composition of the building	Wood Panel							Asbestos siding
Are the windows in good condition	Good							
Are the doors adequate and secure	Good							
Condition of concrete sidewalks and stairs	Fair							Safety Concern
Condition of curbs								
<b>INTERIOR</b>								
Condition of interior flooring	Fair							
Condition of interior walls	Fair							
General cosmetic condition	Good							Cosmetic upgrades via Legacy to make this space functional for school, but marginal overall condition. Upgrades included carpet, interior paint, and appliances. Basement is unusable except for storage, building is in very old barely acceptable condition
If appliances, what condition	Excellent	LEGACY						
Fridge	Excellent	LEGACY						
Dishwasher	Excellent	LEGACY						
Oven/cooktops	Excellent	LEGACY						
Cabinets/counters	Excellent	LEGACY						

Facility Condition Report								
Facility	Age	Location	Square Footage	Overall Condition	Usage	Number of Rooms	New	5 – New - New or like-new condition; no issues to report; no expected failures
St. Ann's	1963	Terreton ID	800.00				Good	4 – good - Good condition; no reported issues or concerns
							Fair	3 – fair - Average wear for building age; not new but no issues to report
							Poor	2 – poor - Worn from use -end of expected lifecycle. Plan for replacement/upgrade
							Critical	1 – critical - Extremely worn or damaged, could be potential safety issues, replacement w/in 2 yrs.
								NA - Not Applicable
	TYPE	5	4	3	2	1		Comments/Recommendations
<b>HVAC</b>								
Condition	Good							Gas forced air, replaced in 2012
Type of air conditioning	None							
<b>ROOF</b>								
Condition	Good							Metal over original asphalt, metal installed in 1999, repaired in 2013
<b>ELECTRICAL</b>								
Condition	Fair							Old wiring w/numerous non-code compliant conditions.
Lighting	Fair							Fluorescent lighting throughout
<b>PLUMBING</b>								
Condition	Good							Sewer line from builing to street replaced in 2017
<b>SECURITY</b>								
Condition	None							
<b>EXTERIOR</b>								
Exterior Condition	Good							Paint new 2012, windows new 2016, new flatwork 2017
Are the windows in good condition	Good							
Are the doors adequate and secure	Good							
Condition of concrete sidewalks and stairs	Fair							Safety Concern-no railing on stairs
Condition of parking lot and any pavement	Fair							Dirt parking lot
<b>INTERIOR</b>								
Condition of interior flooring	Fair							Flooring is in gernaly decent shape.
Condition of interior walls	Fair							Need general area painting done.
General cosmetic condition	Good							Repainted exterior in 2012, windows replaced in 2016, generally in good shape with the exception of the very dated kitchen.
If appliances, what condition	Critical							Kitchen appliances, cabinets, very old and don't meet parish standards







CTK HALL

Room	Sq Ft.
101	377
102	396
103	332
104	332
105	326
106	329
107	325
108	291
109	300
110	386
111	211
112	112
113	20
114	33
115	176
116	176
117	688
118	3638
119	283
120	251
121	980
122	153
123	140
124	20
125	160
126	39
127	78
<b>10552</b>	

CTK Rectory

Room	Sq Ft.
1-101	192
1-102	203
1-103	66
1-104	220
1-105	155
1-106	166
1-107	37
1-108	39
1-109	151
1-110	158
B-101	186
B-102	147
B-103	38
B-104	272
B-105	201
B-106	117
B-107	331
2679	

HR Rectory

Room	Sq Ft.
1-101	320
1-102	204
1-103	286
1-104	161
1-105	116
1-106	107
1-107	162
1-108	165
1-109	93
2-101	332
2-102	157
2-103	39
2-104	57
2-105	33
2-106	111
2-107	226
2-108	140
2-109	116
2-110	188
B-101	426
B-102	179
B-103	137
B-104	161
B-105	56
B-106	150
B-107	52
B-108	226
B-109	227
B-110	487
B-111	209
<b>5323</b>	

HR Church

Room	Sq Ft.
Loft	416
Bathroom	32
Bathroom	63
Cry Room	162
Vestibule	291
Sacristy	964
Parish Office	
Room	Sq Ft.
1-101	272
1-102	196
1-103	217
1-104	185
1-105	190
1-106	330
1-107	86
1-108	34
2-101	244
2-102	111
2-103	111
2-104	111
2-105	226
2-106	111
2-107	111
2-108	111
2-109	111
2-110	111
2-111	111
B-101	220
B-102	30
B-103	52
B-104	484
B-105	58
B-106	308
B-107	121
<b>4252</b>	

HR Hall

Room	Sq Ft.
Main Hall	6700
Kitchen	
Upstairs	549
Boiler Rm	
Bathroom	7249
Learning Center	
Room	Sq Ft.
1-101	300
1-102	349
1-103	36
1-104	346
1-105	300
1-106	45
B-101	248
B-102	187
B-103	102
B-104	327
B-105	288
B-106	45
B-107	296
<b>2869</b>	

HR School

Room	Sq Ft.
Reception/Princ	354
Computer room	286
Library	
Mechanical	86
Girls RR	268
Boys RR	223
Rm 3	892
Rm 5	689
Rm 5A	88
Storage	34
Main Hall	2920